































	9	10	11	12
H min	1710mm	1900mm	2090mm	2280mm
H max	2115mm	2350mm	2585mm	2820mm








 1x 	 11x 	 1x $\varnothing 60 \times 1000 \times 4 \text{ mm}$	 1x 	 12x $\varnothing 108 \times 200 \text{ mm}$	 24x $\varnothing 115 \times 3 \text{ mm}$
 1x $\varnothing 100 \times 3 \text{ mm}$	 12x $\varnothing 22 \times 2 \times 1275 \text{ mm}$	 11x $\varnothing 22 \times 1 \times 1175 \text{ mm}$	 7x $\varnothing 22 \times 2 \times 1030 \text{ mm}$	 2x $\varnothing 22 \times 1 \times 1050 \times 210 \text{ mm}$	 1x $\varnothing 60 \text{ mm}$
 2x $\varnothing 28 \times 2 \times 50 \text{ mm}$	 1x $\varnothing 40 \times 3 \times 6000 \text{ mm}$	 1x $\varnothing 40 \times 2 \times 975 \text{ mm}$	 2x 	 4x $M20 \times 1000 \text{ mm}$	 4x $M20 \text{ DIN } 6334$
 1x 	 38x 	 76x $\varnothing 5 \times 30 \text{ mm}$		 4x $\varnothing 12 \text{ mm}$	 14x $\varnothing 8 \text{ mm}$
 64x $\varnothing 4,2 \times 19 \text{ mm}$		 7x $M20 \text{ DIN-EN } 24035$	 32x $\varnothing 22 \text{ mm}$		
 4x $M8 \times 50 \text{ mm}$	 12x $\varnothing 6 \times 50 \text{ mm}$	 8x $\varnothing 6 \times 30 \text{ mm}$		 1x $\varnothing 40 \text{ mm}$	 2x $\varnothing 40 \text{ mm}$
 48x $\varnothing 4 \times 25 \text{ mm}$	 3x $M8 \times 20 \text{ mm}$	 2x $M6$	 2x $M6$		












4





5





6

