

N1	11x	N2	1x	N3	1x	N4	1x	N5	11x	N6	10x
								ø60mm		ø22mm	
N7	1x	N7a	11x	N8	10x	N9	20x	N10	4x	N11	8x
				ø22x1x1100mm				M10		M8	
N12	20x	N13	24x	N14	2x	N15	72x	N16	60x	N17	10x
				M10x8mm		ø6x30mm		ø5x40mm		ø4x25mm	
N18	20x	N19	10x	N20	10x	N21	20x	N22	8x	N23	2x
				M10		M6x6mm		M8x70mm		M10x70mm	
N24	8x	N25	1x	N26	2x	N27	10x	N28	10x	N29	6x
		ø40x3,5x4000mm		ø40mm						ø6x12mm	
N30	3x	N31	30x	N32	30x	N1-N32 OK? START					
				M6x14mm		H:h $h_{max} = 226mm$ $h_{min} = 172mm$ $H_{max} = 2938mm$ $(13 \times h_{max})$ $H_{min} = 2236mm$ $(13 \times h_{min})$					







